



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
1	4502242	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
2	4504986	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
3	4505113	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-27	Wiring Harness Test bench	APS 2300
4	4506061	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
5	7005339	HARNESSE ASSEMBLY, APU	49	Hamilton Sundstrand	repair,inspection/test	49-15-01	Wiring harness testbench	Boeing 787
6	7005340	HARNESSE ASSEMBLY, FUEL POWER MODULE	49	Hamilton Sundstrand	repair,inspection/test	49-15-02	Wiring harness testbench	Boeing 787
7	7006094	HARNESSE ASSEMBLY, APU	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-15-01	ACM Test Bench	Embraer 170/190
8	7006095	HARNESSE ASSEMBLY, FUEL POWER MODULE	49	Hamilton Sundstrand	repair,inspection/test	49-15-02	Wiring harness testbench	Boeing 787
9	1000700-2	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
10	1000700-3	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
11	1000700-4	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
12	1000700-5	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
13	1000700-6	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
14	1000700-7	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	Wiring harness testbench	Airbus A330/340
15	107484-2	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
16	107484-3	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
17	107484-4	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
18	107484-5	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
19	107484-6	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
20	107484-6	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
21	107484-7	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
22	107484-7	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
23	107492-1	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
24	107492-2	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
25	107492-3	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
26	107492-5	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
27	107492-6	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
28	107492-6	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
29	23E59-2	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
30	23E59-3	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
31	23E59-4	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
32	23E59-5	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
33	23E59-6	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
34	23E59-7	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
35	23E59-7M	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
36	23E59-8	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
37	23E59-9	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
38	3202222-1	VALVE, BLEED AIR CHECK	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-89	Low Flow Test Bench	Boeing 737
39	3202854-1	APU CHECK VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-53-69	Low Flow Test Bench	GTCP 331-500
40	320548-2	VALVE, SOLENOID ASSY	36	Honeywell	repair,modification,overhaul,inspection/test	36-12-35	Low Flow Test Bench	Boeing 737
41	320625-4	VALVE, PRESSURE RELIEF	75	Whittaker	repair,modification,overhaul,inspection/test	75-31-01	Low Flow Test Bench	B747-400
42	320625-6	VALVE, PRESSURE RELIEF	75	Whittaker	repair,modification,overhaul,inspection/test	75-31-01	Low Flow Test Bench	B747-400
43	320625-7	VALVE, PRESSURE RELIEF	75	Whittaker	repair,modification,overhaul,inspection/test	75-31-01	Low Flow Test Bench	B747-400
44	3214446-4	VALVE, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-12-45	Low Flow Test Bench	Boeing 737
45	3214552-4	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737
46	3214552-5	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
47	3214552-6	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737
48	3215618-2	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
49	3215618-3	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
50	3215618-4	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
51	3215618-5	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
52	3283076-2	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
53	3283076-3	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
54	3283076-4	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
55	3283076-5	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
56	3289562-4	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
57	3289562-5	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
58	3289562-5	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
59	3289562-6	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
60	3289562-6	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
61	3289562-7	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
62	3289562-7	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
63	3289630-2	VALVE, 3" DIAM. STARTER CONTROL	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-27	High Flow Test Bench	Boeing 737
64	3289630-3	VALVE, 3" DIAM. STARTER CONTROL	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-27	High Flow Test Bench	Boeing 737
65	3289630-4	VALVE, 3" DIAM. STARTER CONTROL	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-27	High Flow Test Bench	Boeing 737
66	3289630-5	VALVE, 3" DIAM. STARTER CONTROL	80	Honeywell	inspection/test	80-11-27	#N/A	Boeing 787
67	3290694-2	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
68	3290694-3	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
69	3290694-4	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
70	3290694-5	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
71	3290694-6	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
72	3290694-7	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
73	3290694-8	VALVE, PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-47	High Flow Test Bench	A330 / A340
74	3291172-1	VALVE, 4" PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-67	High Flow Test Bench	B747-400
75	3291172-2	VALVE, 4" PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-67	High Flow Test Bench	B747-400
76	3291172-3	VALVE, 4" PNEUMATIC BUTTERFLY SHUTOFF	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-67	High Flow Test Bench	B747-400
77	3291214-2	VALVE APU BLEED AIR 3.5"	49	Honeywell	repair,modification,inspection/test	49-52-29	High Flow Test Bench	GTCP 131-9B
78	3291432-1	VALVE LOAD CONTROL 3.5"	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-35	High Flow Test Bench	GTCP 131-9A
79	3505448-5-1	STARTER, PNEUMATIC ENGINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-11	Air Turbine Starter Test bank	B747-400
80	3505814-3	AIR TURBINE STARTER	49	Honeywell	repair,modification,inspection/test	49-42-01	Starter Test Bench	GTCP 331-500
81	3505945-10	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
82	3505945-10	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
83	3505945-11	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
84	3505945-11	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
85	3505945-12	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
86	3505945-12	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
87	3505945-6	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
88	3505945-7	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
89	3505945-8	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
90	3505945-9	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
91	3505945-9	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
92	3614295-1	Cooling Valve	49	Allen aircraft products	inspection/test	49-51-97	Low Flow Test Bench	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
93	3614295-2	Cooling Valve	49	Allen aircraft products	inspection/test	49-51-97	Low Flow Test Bench	Boeing 787
94	3614295-3	Cooling Valve	49	Allen aircraft products	inspection/test	49-50-04	Low Flow Test Bench	Boeing 787
95	3616960-2	COOLING FAN ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-52-41	APU Test Cell	GTCP 331-350
96	3616960-3	COOLING FAN ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-52-41	APU Test Cell	GTCP 331-350
97	3800454-1	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
98	3800454-2	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
99	3800454-3	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
100	3800454-4	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
101	3800454-5	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
102	3800454-6	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
103	3800550-1	Gas Turbine Engine Assembly	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-57	APU Test Cell	Boeing B777
104	3800702-1	Gas Turbine Engine -9B	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-95	APU Test Cell	Boeing 737
105	3800708-1	Pneu and Shaft Power Gas Turbine Engine -9A	49	Honeywell	repair,modification,overhaul,inspection/test	49-27-29	APU Test Cell	Airbus A320
106	3876217-1	Inlet Pressure Transducer	49	Honeywell	inspection/test	49-52-15	APU Test Cell	Boeing 787
107	3876218-1	Total Pressure Transducer	49	Honeywell	inspection/test	49-52-15	Low Flow Test Bench	Boeing 787
108	3876219-2	Differential Transducer	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-15	Low Flow Test Bench	Boeing 787
109	3876225-2	Sensor Pressure	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
110	3876226-1	Sensor Press Tot	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
111	3876227-2	Sensor Pressure Differential	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
112	3888297-1	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
113	3888297-2	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
114	3888297-3	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
115	3888364-3	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-26-57	Wiring Harness Test bench	GTCP 331-500
116	3888364-4	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-26-57	Wiring Harness Test bench	GTCP 331-500
117	3888438-1	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-11-13	Wiring Harness Test bench	GTCP 131-9A
118	3888448-1	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-11	Wiring Harness Test bench	GTCP 131-9B
119	3888448-2	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-11	Wiring Harness Test bench	GTCP 131-9B
120	3888449-1	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-12	Wiring Harness Test bench	GTCP 131-9B
121	3888449-2	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-12	Wiring Harness Test bench	GTCP 131-9B
122	3888559-1	WIRING HARNESS	49	Honeywell	repair,modification,overhaul,inspection/test	49-25-95	Wiring harness testbench	Airbus A330/340
123	3888571-1	WIRING HARNESS	49	Honeywell	repair,modification,overhaul,inspection/test	49-25-95	Wiring Harness Test bench	Airbus A320
124	4500001A	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
125	4500001B	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
126	4500001C	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
127	4502242A	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	APU Test Cell	Airbus A320
128	4502242B	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Airbus A320
129	4502242C	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
130	4505001A	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	2300-1 EM	APU Test Cell	Embraer 170/190
131	4505001B	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	2300-1 EM	APU Test Cell	Embraer 170/190
132	540-0712-1	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
133	540-0712-2	VALVE, ASSEMBLY SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-10-06	Low Flow Test Bench	B747-400
134	67-2906-001	VALVE, MOTOR OPERATED SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-09-02	Low Flow Test Bench	Boeing 737
135	67-2906-002	VALVE, MOTOR OPERATED SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-09-02	Low Flow Test Bench	Boeing 737
136	7001425-3	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
137	7002532-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	Actuator Test Box	Boeing 787
138	7002532-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
139	7002532-7	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
140	7002532-8	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
141	7002534-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
142	7002534-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
143	7002535-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
144	7002536-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
145	7002537-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
146	7002537-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
147	7002541-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
148	7002541-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
149	7002542-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
150	7002543-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
151	7002543-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
152	7002544-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
153	7002544-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
154	7002545-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
155	7002545-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
156	7002546-2	INSULATION - ADD HEAT VALVE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
157	7002546-3	INSULATION - ADD HEAT VALVE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
158	7002547-3	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
159	7002547-4	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
160	7002548-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
161	7002550-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
162	7002551-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
163	7002552-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
164	7002554-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
165	7002555-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
166	7002557-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
167	7002557-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
168	7002558-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
169	7002558-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
170	7002559-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
171	7002559-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
172	7002560-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
173	7002560-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
174	7002561-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
175	7002562-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
176	7002563-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
177	7002568-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
178	7002568-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
179	7002814-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
180	7002815-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
181	7002816-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
182	7002817-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
183	7002818-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
184	7002819-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
185	7002820-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
186	7002821-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
187	7002822-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
188	7002828-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
189	7002907H02	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
190	7002907H03	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
191	7002907H04	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
192	7002907H05	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
193	7002907H06	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
194	7002907H07	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
195	7002907H08	AUXILIARY POWER UNIT APS5000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
196	7002907H09	APU APS5000A	45	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	4510762	APU Test Cell	Boeing 787
197	7005336H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
198	7005336H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
199	7005336H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
200	7005336H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
201	7005336H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
202	7005336H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
203	7005336H07	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
204	7005336H08	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
205	7005336H09	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
206	7005336H10	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
207	7005337H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
208	7005337H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
209	7005337H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
210	7005337H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
211	7005337H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
212	7005337H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
213	7005337H07	MODULE, CAC, LEFT PACK INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
214	7005337H08	MODULE, CAC, LEFT PACK OUTBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
215	7005337H09	MODULE, CAC, LEFT PACK INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
216	7005337H10	MODULE, CAC, LEFT PACK OUTB	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
217	7006094A	HARNESSE ASSEMBLY, APU	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-15-01	Megger and Bonding Tester	Boeing 787
218	7010071H01	Check Valve, Flight Deck	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-52	Low Flow Test Bench	Boeing 787
219	7010072H01	Check Valve, Ground Connect	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-27	Low Flow Test Bench	Boeing 787
220	7010074H01	Check Valve, Alternate Ventilation System 2,5 Inch	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-23	Low Flow Test Bench	Boeing 787
221	7010075H01	Check Valve, 7.0 Inch	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-26	Low Flow Test Bench	Boeing 787
222	7010101H07	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
223	7010101H08	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
224	7010101H09	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
225	7010102H02	FLOW SENSOR - CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-90	Low Flow Test Bench	Boeing 787
226	7010102H03	Boosted Venturi Flow Sensor	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-90	Low Flow Test Bench	Boeing 787
227	7010104-172	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
228	7010104H03	ADD Heat Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-69	Low Flow Test Bench	Boeing 787
229	7010105H01	Check Valve, CAC Outlet	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-91	Low Flow Test Bench	Boeing 787
230	7010105H02	Check Valve, CAC Outlet	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-91	Low Flow Test Bench	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
231	7010121H03	Air Cycle Machine	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-55	ACM Test Bench	Boeing 787
232	7010126H04	Terminal Box Assembly	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-98	N/A	Boeing 787
233	7010126H05	Terminal Box Assembly	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-98	N/A	Boeing 787
234	7010128-115	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
235	7010128H03	Air Cycle Machine Bypass Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-70	Low Flow Test Bench	Boeing 787
236	7010129H01	50 PSIA Pressure Sensor	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-85	Low Flow Test Bench	Boeing 787
237	7010129H02	SENSOR PRESSURE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-85	Low Flow Test Bench	Boeing 787
238	7010131H03	Economy Cooling Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-71	Low Flow Test Bench	Boeing 787
239	7010134H01	Check Valve, Ram Air	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-30	Low Flow Test Bench	Boeing 787
240	7010149H02	Compact Mixer	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-60	Low Flow Test Bench	Boeing 787
241	7010149H03	Compact Mixer	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-60	Low Flow Test Bench	Boeing 787
242	7010157H11	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
243	7010157H21	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
244	7010157H31	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
245	7010159H01	Dual-coil speed sensor	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-75	Wiring harness testbench	Boeing 787
246	7010163H03	Trim Air Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-72	Low Flow Test Bench	Boeing 787
247	7010173-133	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
248	7010226H11	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
249	7010226H21	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
250	7010226H31	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
251	7010304H02	OVERRIDE VALVE - AFT	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-06	Low Flow Test Bench	Boeing 787
252	7010309H02	EECS SHUTOFF VALVE - 9 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-07	Low Flow Test Bench	Boeing 787
253	7010403H02	FCAC OVERRIDEVALVE - AFT	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-09	Low Flow Test Bench	Boeing 787
254	7010409H02	CHS INTERMEDIATE POSITIONING 7 INCH VALV	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-10	Low Flow Test Bench	Boeing 787
255	7010413H02	CHS SHUTOFF VALVE - 7 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-24-05	Low Flow Test Bench	Boeing 787
256	7010703H02	SHUTOFF VALVE - 3 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-44-02	Low Flow Test Bench	Boeing 787
257	7010906H02	ADS SHUTOFF VALVE - 4.5 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-29-04	Low Flow Test Bench	Boeing 787
258	7011003-109	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
259	7012001-108	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
260	7012001H02	Shutoff Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-11-10	Low Flow Test Bench	Boeing 787
261	7012001H03	Shutoff Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-11-10	Low Flow Test Bench	Boeing 787
262	7012003-114	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
263	7012003H02	Ram Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-07	Low Flow Test Bench	Boeing 787
264	7012003H03	Ram Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-07	Low Flow Test Bench	Boeing 787
265	7012004H01	Check Valve, 2.5 Inch	47	Hamilton Sundstrand	repair,modification,inspection/test	47-14-02	Low Flow Test Bench	Boeing 787
266	7012005H02	Flow Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-08	Low Flow Test Bench	Boeing 787
267	7012005H03	Flow Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-08	Low Flow Test Bench	Boeing 787
268	7012007H03	Shutoff Motor Cooling Switch Indication Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-02	Low Flow Test Bench	Boeing 787
269	7012060H02	1 INCH remote valve	47	Hamilton Sundstrand	inspection/test	47-21-01	Nitrogen Test Bench	Boeing 787
270	7012060H03	1 INCH remote valve	47	Hamilton Sundstrand	inspection/test	47-21-01	Nitrogen Test Bench	Boeing 787
271	7012070H03	Actuator Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-09	Nitrogen Test Bench	Boeing 787
272	7012075H01	Ejector pump	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-04	Nitrogen Test Bench	Boeing 787
273	7012080H02	1.5 INCH remote valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-06	Nitrogen Test Bench	Boeing 787
274	7100988-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	Nitrogen Test Bench	Boeing 787
275	7101256-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
276	7101299-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
277	7101299-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
278	7101586-1	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
279	7101586-2	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
280	7101666-1	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
281	7101666-2	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
282	7101668-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
283	7102532-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
284	7102532-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
285	7102532-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
286	7102532-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
287	7102532-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
288	7102532-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
289	7102534-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
290	7102534-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
291	7110101H01	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
292	7110101H02	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
293	7110101H03	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
294	7110121H01	Air Cycle Machine	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-81	ACM Test Bench	Boeing 787
295	7110149H01	COMPACT MIXER	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-21	Low Flow Test Bench	Boeing 787
296	7111057-101	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
297	7112060H01	1 INCH pedestal valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-11	Actuator Test Box	APS2300
298	7112075H01	Ejector pump	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-12	Nitrogen Test Bench	Boeing 787
299	7115336H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
300	7115336H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
301	7115336H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
302	7115336H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
303	7115336H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
304	7115336H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
305	7115336H07	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
306	7115336H08	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
307	7115337H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
308	7115337H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
309	7115337H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
310	7115337H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
311	7115337H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
312	7115337H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
313	7115337H07	CAC MODULE PACK LEFT INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
314	7115337H08	CAC PACK MODULE LEFT OUTBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
315	7200055-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	Megger and Bonding Tester	Boeing 787
316	7200059-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
317	7200060-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
318	7200061-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
319	7200062-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
320	7200146-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
321	7200166-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
322	7200169-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:

The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
323	7200169-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
324	7200170-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
325	7200170-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
326	7200171-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
327	7200173-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
328	7200180-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
329	7202532-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
330	7202532-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
331	7202534-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
332	7202534-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
333	7202817-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
334	7212548-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
335	773289-10	CONTROLLER, HIGH PRESSURE	36	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	36-12-02	Low Flow Test Bench	B747-400