



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
1	(M) 4506061-13	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	APS 3200
2	(M) 4506061-16	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	APS 3200
3	(M) 4506061-4	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	APS 3200
4	(M) 4506061-9	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	APS 3200
5	1000700-2	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
6	1000700-3	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
7	1000700-4	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
8	1000700-5	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
9	3202854-1	APU CHECK VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-53-69	Low Flow Test Bench	GTCP 331-500
10	3283076-2	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
11	3283076-3	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
12	3283076-4	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
13	3283076-5	APU STARTER VALVE	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-19	High Flow Test Bench / Low Flow Test Bench	GTCP 331-500
14	3291214-2	VALVE APU BLEED AIR 3.5"	49	Honeywell	repair,modification,inspection/test	49-52-29	High Flow Test Bench	GTCP 131-9B
15	3291432-1	VALVE LOAD CONTROL 3.5"	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-35	High Flow Test Bench	GTCP 131-9A
16	3505814-3	AIR TURBINE STARTER	49	Honeywell	repair,modification,inspection/test	49-42-01	Starter Test Bench	GTCP 331-500
17	3614295-1	Cooling Valve	49	Allen aircraft products	inspection/test	49-51-97	Low Flow Test Bench	Boeing 787
18	3614295-2	Cooling Valve	49	Allen aircraft products	inspection/test	49-51-97	Low Flow Test Bench	Boeing 787
19	3614295-3	Cooling Valve	49	Allen aircraft products	inspection/test	49-50-04	Low Flow Test Bench	Boeing 787
20	3616960-2	COOLING FAN ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-52-41	APU Test Cell	GTCP 331-350
21	3616960-3	COOLING FAN ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-52-41	APU Test Cell	GTCP 331-350
22	3800454-1	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
23	3800454-2	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
24	3800454-3	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
25	3800454-4	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
26	3800454-5	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
27	3800454-6	Gas Turbine Compressor Power Unit	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-11	APU Test Cell	Airbus A330/340
28	3800550-1	Gas Turbine Engine Assembly	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-57	APU Test Cell	Boeing B777
29	3800702-1	Gas Turbine Engine -9B	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-95	APU Test Cell	Boeing 737
30	3800708-1	Pneu and Shaft Power Gas Turbine Engine -9A	49	Honeywell	repair,modification,overhaul,inspection/test	49-27-29	APU Test Cell	Airbus A320
31	3888297-1	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
32	3888297-2	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
33	3888297-3	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-25-95	Wiring Harness Test bench	GTCP 331-350
34	3888364-3	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-26-57	Wiring Harness Test bench	GTCP 331-500
35	3888364-4	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-26-57	Wiring Harness Test bench	GTCP 331-500
36	3888438-1	WIRING HARNESS	49	Honeywell	repair,modification,inspection/test	49-11-13	Wiring Harness Test bench	GTCP 131-9A
37	3888448-1	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-11	Wiring Harness Test bench	GTCP 131-9B
38	3888448-2	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-11	Wiring Harness Test bench	GTCP 131-9B
39	3888449-1	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-12	Wiring Harness Test bench	GTCP 131-9B
40	3888449-2	WIRING HARNESS	49	Fokker Elmo	repair,modification,inspection/test	49-11-12	Wiring Harness Test bench	GTCP 131-9B
41	4500001A	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
42	4500001B	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
43	4500001C	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	3200-1 EM	APU Test Cell	Airbus A320
44	4505001A	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	2300-1 EM	APU Test Cell	Embraer 170/190
45	4505001B	Auxiliary Power Unit System	49	Hamilton Sundstrand	repair,modification,inspection/test	2300-1 EM	APU Test Cell	Embraer 170/190
46	4505113	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-27	Wiring Harness Test bench	APS 2300
47	7001425-3	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
48	7002546-2	INSULATION - ADD HEAT VALVE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
49	7002546-3	INSULATION - ADD HEAT VALVE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
50	7002547-3	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
51	7002547-4	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
52	7002907H02	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
53	7002907H03	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
54	7002907H04	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
Bellsingel 41
1119 NT Schiphol-Rijk
The Netherlands
Tel: (+31 20) 3161730
Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
55	7002907H05	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
56	7002907H06	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
57	7002907H07	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
58	7002907H08	AUXILIARY POWER UNIT APSS000A	49	Hamilton Sundstrand	repair,modification,inspection/test	4510762	APU Test Cell	Boeing 787
59	7005336H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
60	7005336H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
61	7005336H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
62	7005336H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
63	7005336H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
64	7005336H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
65	7005336H07	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
66	7005336H08	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
67	7005336H09	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
68	7005336H10	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
69	7005337H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
70	7005337H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
71	7005337H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
72	7005337H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
73	7005337H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
74	7005337H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
75	7005337H07	MODULE, CAC, LEFT PACK INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
76	7005337H08	MODULE, CAC, LEFT PACK OUTBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
77	7005337H09	MODULE, CAC, LEFT PACK INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
78	7005337H10	MODULE, CAC, LEFT PACK OUTB	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-75	Megger and Bonding Tester	Boeing 787
79	7005339	HARNESS ASSEMBLY, APU	49	Hamilton Sundstrand	repair,inspection/test	49-15-01	Wiring harness testbench	Boeing 787
80	7005340	HARNESS ASSEMBLY, FUEL POWER MODULE	49	Hamilton Sundstrand	repair,inspection/test	49-15-02	Wiring harness testbench	Boeing 787
81	7006095	HARNESS ASSEMBLY, FUEL POWER MODULE	49	Hamilton Sundstrand	repair,inspection/test	49-15-02	Wiring harness testbench	Boeing 787
82	7010071H01	Check Valve, Flight Deck	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-52	Low Flow Test Bench	Boeing 787
83	7010072H01	Check Valve, Ground Connect	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-27	Low Flow Test Bench	Boeing 787
84	7010074H01	Check Valve, Alternate Ventilation System 2.5 Inch	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-23	Low Flow Test Bench	Boeing 787
85	7010075H01	Check Valve, 7.0 Inch	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-26	Low Flow Test Bench	Boeing 787
86	7010101H07	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
87	7010101H08	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
88	7010101H09	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-97	CAC test cell	Boeing 787
89	7010102H02	FLOW SENSOR - CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-90	Low Flow Test Bench	Boeing 787
90	7010103H02	SENSOR - TEMPERATURE	21	Hamilton Sundstrand	inspection/test	21-51-96	N/A	Boeing 787
91	7010104-172	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
92	7010104H03	ADD Heat Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-69	Low Flow Test Bench	Boeing 787
93	7010105H01	Check Valve, CAC Outlet	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-91	Low Flow Test Bench	Boeing 787
94	7010105H02	Check Valve, CAC Outlet	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-91	Low Flow Test Bench	Boeing 787
95	7010121H03	Air Cycle Machine	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-55	ACM Test Bench	Boeing 787
96	7010126H04	Terminal Box Assembly	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-98	N/A	Boeing 787
97	7010126H05	Terminal Box Assembly	21	Hamilton Sundstrand	repair,modification,inspection/test	21-51-98	N/A	Boeing 787
98	7010128-115	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
99	7010128H03	Air Cycle Machine Bypass Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-70	Low Flow Test Bench	Boeing 787
100	7010129H01	50 PSIA Pressure Sensor	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-85	Low Flow Test Bench	Boeing 787
101	7010129H02	SENSOR PRESSURE	21	Hamilton Sundstrand	repair,modification,inspection/test	21-52-85	Low Flow Test Bench	Boeing 787
102	7010131H03	Economy Cooling Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-71	Low Flow Test Bench	Boeing 787
103	7010134H01	Check Valve, Ram Air	21	Hamilton Sundstrand	repair,modification,inspection/test	21-21-30	Low Flow Test Bench	Boeing 787
104	7010149H02	Compact Mixer	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-60	Low Flow Test Bench	Boeing 787
105	7010149H03	Compact Mixer	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-60	Low Flow Test Bench	Boeing 787
106	7010157H11	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
107	7010157H21	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
108	7010157H31	WIRING HARNESS - CACTCS TO CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
 Bellsingel 41
 1119 NT Schiphol-Rijk
 The Netherlands
 Tel: (+31 20) 3161730
 Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
 The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
 EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
109	7010163H03	Trim Air Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-72	Low Flow Test Bench	Boeing 787
110	7010173-133	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
111	7010173H03	Temperature Control Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-19	Low Flow Test Bench	Boeing 787
112	7010176H03	Isolation Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-20	Low Flow Test Bench	Boeing 787
113	7010226H11	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
114	7010226H21	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
115	7010226H31	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-61	Wiring harness testbench	Boeing 787
116	7010227H21	HARNESS	21	Hamilton Sundstrand	repair,inspection/test	21-52-62	Wiring harness testbench	Boeing 787
117	7010304H02	OVERRIDE VALVE - AFT	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-06	Low Flow Test Bench	Boeing 787
118	7010309H02	EECS SHUTOFF VALVE - 9 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-07	Low Flow Test Bench	Boeing 787
119	7010403H02	FCAC OVERRIDEVALVE - AFT	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-09	Low Flow Test Bench	Boeing 787
120	7010409H02	CHS INTERMEDIATE POSITIONING 7 INCH VALV	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-27-10	Low Flow Test Bench	Boeing 787
121	7010413H02	CHS SHUTOFF VALVE - 7 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-24-05	Low Flow Test Bench	Boeing 787
122	7010703H02	SHUTOFF VALVE - 3 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-44-02	Low Flow Test Bench	Boeing 787
123	7010906H02	ADS SHUTOFF VALVE - 4.5 INCH	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-29-04	Low Flow Test Bench	Boeing 787
124	7011003-109	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
125	7011056H03	Temperature Control Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-19	Low Flow Test Bench	Boeing 787
126	7011056H04	Temperature Control Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-19	Low Flow Test Bench	Boeing 787
127	7012001-108	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
128	7012001H02	Shutoff Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-11-10	Low Flow Test Bench	Boeing 787
129	7012001H03	Shutoff Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-11-10	Low Flow Test Bench	Boeing 787
130	7012003-114	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
131	7012003H02	Ram Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-07	Low Flow Test Bench	Boeing 787
132	7012003H03	Ram Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-07	Low Flow Test Bench	Boeing 787
133	7012004H01	Check Valve, 2.5 Inch	47	Hamilton Sundstrand	repair,modification,inspection/test	47-14-02	Low Flow Test Bench	Boeing 787
134	7012005H02	Flow Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-08	Low Flow Test Bench	Boeing 787
135	7012005H03	Flow Control Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-08	Low Flow Test Bench	Boeing 787
136	7101586-1	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
137	7101586-2	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
138	7101666-1	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
139	7101666-2	INSULATION - CAC	21	Hamilton Sundstrand	repair,modification,inspection/test	21-53-98	N/A	Boeing 787
140	7110101H01	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
141	7110101H02	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
142	7110101H03	CABIN AIR COMPRESSOR	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-20	CAC test cell	Boeing 787
143	7110121H01	Air Cycle Machine	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-81	ACM Test Bench	Boeing 787
144	7110149H01	COMPACT MIXER	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-21	Low Flow Test Bench	Boeing 787
145	7111055H02	GCU Temperature Control Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-20	Low Flow Test Bench	Boeing 787
146	7111057-101	Rotary Actuator	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-68	Actuator Test Box	Boeing 787
147	7111057H01	Galley Pressure Control Valve	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-55-20	Low Flow Test Bench	Boeing 787
148	7115336H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
149	7115336H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
150	7115336H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
151	7115336H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
152	7115336H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
153	7115336H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
154	7115336H07	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
155	7115336H08	CAC Module	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
156	7115337H01	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
157	7115337H02	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
158	7115337H03	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
159	7115337H04	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
160	7115337H05	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
161	7115337H06	CAC Module	21	Hamilton Sundstrand	repair,modification,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
162	7115337H07	CAC MODULE PACK LEFT INBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
 Bellsingel 41
 1119 NT Schiphol-Rijk
 The Netherlands
 Tel: (+31 20) 3161730
 Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
 The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
 EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
163	7115337H08	CAC PACK MODULE LEFT OUTBD	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-54-23	Megger and Bonding Tester	Boeing 787
164	810209-10	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
165	810209-11	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
166	810209-2	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
167	810209-3	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
168	810209-4	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
169	810209-5	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
170	810209-6	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
171	810209-7	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
172	810209-8	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
173	810209-9	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-03	ACM Test bench	Boeing B777
174	968214-1	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
175	968214-10	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
176	968214-11	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
177	968214-12	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
178	968214-13	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
179	968214-14	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
180	968214-15	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
181	968214-17	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
182	968214-2	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
183	968214-3	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
184	968214-4	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
185	968214-5	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
186	968214-6	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
187	968214-7	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
188	968214-8	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
189	968214-9	PRESSURE RELIEF VALVE ASSEMBLY	49	Honeywell	repair,modification,inspection/test	49-31-09	Low Flow Test Bench	GTCP 331-350
190	979786-1	VALVE SHUTOFF 4, 5"	49	Honeywell	repair,modification,overhaul,inspection/test	49-50-65	High Flow Test Bench	GTCP 331-350
191	979786-2	VALVE SHUTOFF 4, 5"	49	Honeywell	repair,modification,overhaul,inspection/test	49-50-65	High Flow Test Bench	GTCP 331-350
192	979786-4	VALVE SHUTOFF 4, 5"	49	Honeywell	repair,modification,overhaul,inspection/test	49-50-65	High Flow Test Bench	GTCP 331-350
193	3215618-2	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
194	3215618-5	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
195	3215618-4	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
196	3215618-3	NOSE COWL ANTI ICE VALVE	30	Honeywell	repair,modification,overhaul,inspection/test	30-20-05	Low Flow Test Bench	Boeing 737
197	107492-6	REGULATOR, BLEED AIR	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-95	Low Flow Test Bench	Boeing 737
198	107484-6	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
199	107484-7	REGULATOR, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-93	Low Flow Test Bench	Boeing 737
200	3505945-10	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
201	3505945-9	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
202	3505945-12	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
203	3505945-11	STARTER, ENGINE AIR TURBINE	80	Honeywell	repair,modification,overhaul,inspection/test	80-11-79	Air Turbine Starter Test bank	Boeing 737
204	3289562-5	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
205	3289562-7	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
206	3289562-6	VALVE, 4" DIAM. PRECOOLER CONTROL	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-91	Low Flow Test Bench	Boeing 737
207	3214446-4	VALVE, HIGH STAGE	36	Honeywell	repair,modification,overhaul,inspection/test	36-12-45	Low Flow Test Bench	Boeing 737
208	67-2906-002	VALVE, MOTOR OPERATED SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-09-02	Low Flow Test Bench	Boeing 737
209	67-2906-001	VALVE, MOTOR OPERATED SHUTOFF	24	Honeywell	repair,modification,overhaul,inspection/test	24-09-02	Low Flow Test Bench	Boeing 737
210	3214552-6	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737
211	3214552-5	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737
212	3214552-4	VALVE, PRESSURE REGULATOR AND SHUTOFF	36	Honeywell	repair,modification,overhaul,inspection/test	36-13-87	Low Flow Test Bench	Boeing 737
213	4502242	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
214	4504986	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
215	4506061	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring harness testbench	Airbus A320
216	7006094	HARNESS ASSEMBLY, APU	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-15-01	ACM Test Bench	Embraer 170/190



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
 Bellsingel 41
 1119 NT Schiphol-Rijk
 The Netherlands
 Tel: (+31 20) 3161730
 Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
 The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
 EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
217	1000700-6	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	ACM Test Bench	Embraer 170/190
218	1000700-7	AIR CYCLE MACHINE	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-13	Wiring harness testbench	Airbus A330/340
219	3888559-1	WIRING HARNESS	49	Honeywell	repair,modification,overhaul,inspection/test	49-25-95	Wiring harness testbench	Airbus A330/340
220	3888571-1	WIRING HARNESS	49	Honeywell	repair,modification,overhaul,inspection/test	49-25-95	Wiring Harness Test bench	Airbus A320
221	4502242A	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Airbus A320
222	4502242B	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Airbus A320
223	4502242C	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
224	7002532-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	Wiring Harness Test bench	Boeing 787
225	7002532-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
226	7002532-7	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
227	7002532-8	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
228	7002534-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
229	7002534-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
230	7002535-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
231	7002536-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
232	7002537-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
233	7002537-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
234	7002541-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
235	7002541-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
236	7002542-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
237	7002543-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
238	7002543-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
239	7002544-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
240	7002544-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
241	7002545-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
242	7002545-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
243	7002548-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
244	7002550-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
245	7002551-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
246	7002552-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
247	7002554-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
248	7002555-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
249	7002557-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
250	7002557-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
251	7002558-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
252	7002558-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
253	7002559-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
254	7002559-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
255	7002560-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
256	7002560-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
257	7002561-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
258	7002562-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
259	7002563-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
260	7002568-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
261	7002568-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
262	7002814-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
263	7002815-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
264	7002816-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
265	7002817-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
266	7002818-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
267	7002819-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
268	7002820-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
269	7002821-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
270	7002822-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
 Bellsingel 41
 1119 NT Schiphol-Rijk
 The Netherlands
 Tel: (+31 20) 3161730
 Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
 The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
 EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
271	7002828-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
272	7002907H09	APU APS5000A	45	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	4510762	N/A	Boeing 787
273	7006094A	HARNESS ASSEMBLY, APU	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-15-01	APU Test Cell	Boeing 787
274	7010102H03	Boosted Venturi Flow Sensor	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-51-90	Wiring Harness Test bench	Boeing 787
275	7012007H03	Shutoff Motor Cooling Switch Indication Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-32-02	Low Flow Test Bench	Boeing 787
276	7012070H03	Actuator Valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-09	Nitrogen Test Bench	Boeing 787
277	7100988-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	Nitrogen Test Bench	Boeing 787
278	7101256-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
279	7101299-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
280	7101299-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
281	7101668-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
282	7102532-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
283	7102532-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
284	7102532-3	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
285	7102532-4	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
286	7102532-5	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
287	7102532-6	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
288	7102534-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
289	7102534-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
290	7200055-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
291	7200059-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
292	7200060-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
293	7200061-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
294	7200062-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
295	7200146-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
296	7200166-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
297	7200169-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
298	7200169-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
299	7200170-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
300	7200170-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
301	7200171-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
302	7200173-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
303	7200180-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
304	7202532-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
305	7202532-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
306	7202534-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
307	7202534-2	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
308	7202817-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
309	7212548-1	Insulation Blanket	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-53-98	N/A	Boeing 787
310	M4502242C2	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-04	N/A	Boeing 787
311	M4502242C3	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
312	M4502242C4	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
313	M4502242C5	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
314	M4504986-1	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
315	M4504986-2	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
316	M4504986-3	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
317	M4504986-4	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
318	M4504986-5	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
319	M4506061-1	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
320	M4506061-10	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
321	M4506061-11	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
322	M4506061-12	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
323	M4506061-14	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
324	M4506061-15	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787



COMPONENT CAPABILITY LIST FOR CCAR-145

Repair Station No. F03100312

EPCOR BV
 Bellsingel 41
 1119 NT Schiphol-Rijk
 The Netherlands
 Tel: (+31 20) 3161730
 Fax: (+31 20) 3161777

CCAR-145 Class:

Limited to those accessories listed per "Component Capability List for CCAR-145", identified as EPCOR Form 186, as revised and approved by the Civil Aviation Administration of China.

Notes:
 The company name stated in the OEM column can differ from the name as printed in CMM/OHM as a result of recent acquisitions
 EPCOR CCAR-145 capability list items are also approved by EASA / FAA / TCCA, please note that for other authorities limitations on this list may be applicable

#	Main P/N:	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
325	M4506061-16	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
326	M4506061-2	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
327	M4506061-3	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
328	M4506061-4	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
329	M4506061-5	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
330	M4506061-6	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
331	M4506061-7	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	inspection/test	49-10-04	Wiring Harness Test bench	Boeing 787
332	M4506061-8	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
333	M4506061-9	Engine Control Wiring Harness Assembly	49	Hamilton Sundstrand	inspection/test	49-10-06	Wiring Harness Test bench	Boeing 787
334	3289630-5	VALVE, 3" DIAM. STARTER CONTROL	80	Honeywell	inspection/test	80-11-27	Wiring Harness Test bench	Boeing 787
335	3876217-1	Inlet Pressure Transducer	49	Honeywell	inspection/test	49-52-15	High Flow Test Bench	Boeing 787
336	3876218-1	Total Pressure Transducer	49	Honeywell	inspection/test	49-52-15	Low Flow Test Bench	Boeing 787
337	3876219-2	Differential Transducer	49	Honeywell	repair,modification,overhaul,inspection/test	49-52-15	Low Flow Test Bench	Boeing 787
338	3876225-2	Sensor Pressure	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
339	3876226-1	Sensor Press Tot	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
340	3876227-2	Sensor Pressure Differential	49	Honeywell	repair,modification,overhaul,inspection/test	49-26-85	Low Flow Test Bench	Boeing 787
341	7010159H01	Dual-coil speed sensor	21	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	21-52-75	Low Flow Test Bench	Boeing 787
342	7012075H01	Ejector pump	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-04	Low Flow Test Bench	Boeing 787
343	7112060H01	1 INCH pedestal valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-11	Nitrogen Test Bench	APS2300
344	7012080H02	1.5 INCH remote valve	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-06	Nitrogen Test Bench	APS2300
345	7012060H02	1 INCH remote valve	47	Hamilton Sundstrand	inspection/test	47-21-01	Nitrogen Test Bench	Boeing 787
346	7012060H03	1 INCH remote valve	47	Hamilton Sundstrand	inspection/test	47-21-01	Nitrogen Test Bench	Boeing 787
347	7112075H01	Ejector pump	47	Hamilton Sundstrand	repair,modification,overhaul,inspection/test	47-21-12	Nitrogen Test Bench	Boeing 787